CLUB REPAIR PROGRAM

We're excited to offer in-house Club Repair at Sycamore Ridge! Please contact the Golf Shop at 913-592-5292 for additional details. For specific inquiries, please reach out to David Miller at dmiller@oriongolf.com.





CLUB REPAIR SERVICES AND PRICING

Service	Price Per Club
Reshaft (iron or wood)	\$20 (20% discount applied to 6 or more clubs)
Remove Shaft/Adapter Only	\$10
Remove Broken Shaft	\$12
Fix Loose Head (wood or iron)	\$15
Remove Shaft Rattle	\$10
Reshaft Putter	\$10 (\$5 additional charge for single or double bend shaft)
Install Adapter	\$10 (Install only. Additional cost to pull existing adapter)
Loft/Lie Adjustment (irons/wedges only)	\$5 (\$20 per set to check only)
Lengthen Club	\$10
Shorten Club	\$5
Adjust Swing Weight (Lead Tape)	\$5
Adjust Swing Weight (Internal Weight - irons/wedges)	\$15
Change Ferrule	\$10
Grind Wedge	\$30
Save Grip	\$3
Custom Stamping	\$25 (Up to 9 Letters, ask regarding additional lettering)
Paint Fill	\$10 (Up to 2 colors. \$35 for 4 or more clubs. Ask regarding additional colors)

Service cost is for labor only. Customer will need to provide or pay for club components (shafts, grips, adapters).